









# Product Overview Resettable Fuses

[www.schurter.com/en/pg01\\_1](http://www.schurter.com/en/pg01_1)



	Type	I hold max	Rated_Voltage IEC V max					
<b>Style: Radial Leaded PTC-Fuse</b>								
	<b>PFRA</b> Radial Leaded Fuse, PTC, 60 VDC	11 A	60.0 VDC					• • • • •
	<b>PFRY</b> Radial Leaded Fuse, PTC, 72 VDC	3.75 A	72.0 VDC					• • • • •
<b>Style: Surface Mount Fuse</b>								
	<b>PFNF</b> Surface Mount Fuse, PTC, 1206 footprint, 3.2 x 1.6 mm, 30 VDC	2 A	30.0 VDC					• • • • •
	<b>PFUF</b> Surface Mount Fuse, PTC, 1210 footprint, 3.2 x 2.6 mm, 30 VDC	1.5 A	30.0 VDC					• • • • •
	<b>PFMF</b> Surface Mount Fuse, PTC, 1812 footprint, 4.6 x 3.2 mm, 60 VDC	2.6 A	60.0 VDC					• • • • •
	<b>PFDF</b> Surface Mount Fuse, PTC, 2018 footprint, 5.1 x 4.6 mm, 60 VDC	0.55 A	60.0 VDC					• • • • •
	<b>PFSM</b> Surface Mount Fuse, PTC, 2920 or 3425 footprint, 60 VDC	2.6 A	60.0 VDC					• • • • •
	<b>PFHT</b> Surface Mount Fuse, PTC, 2920 or 3425 footprint, 16 VDC, up to 125 °C	1.6 A	16.0 VDC					• • •